

GENERAL RISK ASSESSMENT

Cornerstone Vocational Training Ltd

70 Price Street, Birkenhead, CH41 3QZ

Location: 70 Price Street

| | | |
|---|--|-------------------------------------|
| Title : Fitting interior units | Date of Assessment : 08/11/2021 | Risk Assessor : Brendan Bell |
| Risk Assessment Reference : K02 | People involved in making this assessment : Brendan Bell, Ian Jones, Michael Courtenay, Learners (Students) | |
| Task/ Process : Fitting assembled units together | People at Risk : Employees, Children & Young Persons | |

Hazard : Manual handling Assembled units range 300mm wide to 1000mm and all are 600mm deep and 720mm high. When moving or lifting there is a danger of musculoskeletal injury through using incorrect moving and lifting techniques.

Control Measures:

1. Work within a team of two to moving the assembled units. Follow manual handling techniques and always wear the correct PPE

Hazard : Repetitive Movements Units are connected together with Philips head screws which are tightened with a Philips screwdriver. The hinges on the doors are also fixed with Phillips head screws and fixed with a screwdriver. These actions may cause repetitive strain injuries

Control Measures:

1. Take regular breaks when connecting units and fixing the doors

| | |
|--|--------------------------------|
| Documents Associated with this Risk Assessment: | |
| Review Date : 08/11/2022 | Reviewer : Brendan Bell |